## **4T40E-PRT:** Saves 3 Valve Bodies

Hello Mechanic and Shop: Planet Burnup, Codes 1887 & 742, Burned Forward or Reverse Friction, Overheating [Burned Fluid]. Almost everything that happens to this trans, except molded seals falling off clutch pistons, is caused by wear in PR Valve Bore. Fix it while you have it so you won't get to do it again free.

While reaming pour oil here.

Why?: Inboard end of PR bore wears out. This causes the circuit to make HIGH line pressure all the time. Pumps will stand high line for short bursts, but are not designed to handle all time HIGH pressure.



**2.** Dip this end in oil.

Reamer

This end into Guide.



1 Install **Snap Ring** into groove.

**See Wear?** Install PR valve all the way. Move it rightward until it disappears here. Hook valve with bent wire and wiggle.

**Valve Must NOT Wiggle!** 



Guide

Hook with wire here.

Snap Ring

**Turn SLOW** 

PR Valve



"We love this FIX Really works Great" Mr Shift

- Insert Reamer and Guide into bore until Snap Ring touches casting.
  Turn Reamer SLOWLY (1/4 speed) with drill motor.
- 4. Install new PR Valve, Spring Seat and ORANGE spring. Reinstall the original bumper spring, boost valve and bushing.



Hump installs into PR spring

ORANGE

Bumper Spring Boost valve

e Bushing

Worn out from 50,000 miles up. It won't heal. Choose: You FIX this one. OR get a new one.

**OVER** 



