

Ford 5.4L V8 Engines Engine Installation Bulletin

Ford 5.4L Solenoid TSB

This TSB is to inform you of the possible concern on your Ford 5.4L engine. We suggest that the cam phaser solenoids be updated. We have included the solenoids with your engine. We have updated the solenoids to help address possible potential issues surrounding a rough running, intermittent rattle noise when engine is at operating temperature.

Ford has a TSB 12-7-10 surrounding this engine concerned. Once the new solenoids are installed, please flash the PCM for updates as well to ensure a correctly running engine.

