Installation Instructions for 80528
Digital Compression Gauge Reset

Installation Instructions:

1) Press on/off switch.
2) If upon turning the gauge on, a false reading occurs, due to fluctuations in temperature or atmospheric conditions during shipping or other transportation, press and hold the on/off button until four zero's are displayed.
3) Release the on/off button and 0.0 will appear.
4) The gauge is re-set.