Jeep / AMC 4.0 L engines
Engine Installation Bulletin

Contamination/Foreign debris

Contaminants(broken pieces of pistons, rings, and/or valve seats) from a previous failure may find their way into the induction system of these engines. When this occurs the potential for immediate damage to the new remanufactured engine is high and may result in a non-warrantable failure.

ENSURE THERE IS NO FOREIGN DEBRIS IN THE INTAKE MANIFOLD BEFORE IT IS INSTALLED ON THIS NEW ENGINE.

