

Installation Instructions for 40500, 40504, 40506, 40070, 40071 & 40072 Replacement Magnetic Pickup

This replacement pickup is designed for use on the distributor part numbers shown above. The pickup is similar in design to the OEM pickup, but doesn't fit OEM distributors, Mopar Performance Distributors & other brand distributors since they may have the pickup riveted to the advance plate.

The recommended air gap between the pickup and the reluctor wheel is .006" to .012". Check the gap on all 8 cylinders since there could be some minor differences and make adjustments where necessary.



1-800-345-4545 jeps.com