SK[®] U660E

Corrects/Prevents/Reduces

For Professional Use Only!



Shuttle shift, flare on 2-3 shift, slips with throttle in 3rd and/or 4th, TCC slip codes.


Fits:

Toyota: U660 6 speed:


Avalon 08-10 3.5L, Camry 07-12 3.5L, Highlander 09-12 3.5L, RAV4 09-12 2.0, 2.2,& 3.5L, Sienna 11-12 3.5L, Venza 09-11 3.5L

Lexus: U660 6 speed:

ES 350 07-12 3.5L RX 350 10-12 3.5L



This Product Does Not Fit U760E Models! Order SK®U760E



Tech Note:


Always mark the current locations of check balls, retainers etc. to insure they are returned to their original locations even if they differ from what is shown. This is a typical layout of these valve body's. Use care in disassembling.

Planetary failure always REQUIRES a complete strip and cleaning of the valve-body!



Accumulator Body Repairs

Pay Attention to Small Part Locations!







Plate Updates

Help This Trans Stay Cool! Do these steps!


Step 2

Enlarge Lower Body bottom separator plate hole "B" with .055 drill provided.



U660E Accumulator Body Separator Plate

Step 1Enlarge main separator plate hole "A" with .055 drill provided.



This page ends the U660E repair work. Always reassemble any loose small parts the way you found them.