

Spohn Performance, Inc.

494 E Lincoln Ave Myerstown, PA 17067

1-888-365-6064 www.spohn.net

**Part# SRK-S10-8295 – Steering Linkage Rebuild Kit
1982-1992 GM S-10/S-15 (2WD)**

Kit Components

<u>Qty</u>	<u>Part #</u>	<u>Description</u>
1	K6187T	Idler Arm
2	ES2033RL	Outer Tie Rod End
2	ES2034RL	Inner Tie Rod End
1	984	Tie Rod Adjusters
1	DS1047	Center Link

Notes:

- One end of the tie rod adjuster has hash marks. That end is LH threads and the other end is RH threads.
- Use anti-seize compound on all threads (very important, do not skip!).
- The tie rod ends should have a minimum of 7/8" of thread engagement inside of the tie rod adjusters for proper safe thread engagement.