

TITAN

*How to replace the Lithium Battery from your
Wide-lens Auto Darkening Welding Helmet*

TEKZ




**For MODEL #s:
41262, 41265, 42166, & 41267**



STEP 1:
Locate battery holders inside of helmet labeled
"+ cell" (holders are located on both sides)



STEP 2:
Slide out battery holder firmly towards you to
expose battery



STEP 3:
Replace battery and snap holder back into position
Repeat steps: 1-3 on opposite side of the helmet

**** BATTERY REQUIREMENT: Requires (2) CR2450 battery type ****

Distributed by Star Asia-USA, LLC

6528 S 216th, Kent, WA 98032

(253) 735-5355 • Toll Free: 1-800-386-0191 Fax: 1-800-386-0196

email: info@titan-us.com www.titan-us.com

Feb 10, 2011