



PART 23556

Pulley comes with a .10 thick spacer to be installed between the pulley and the alternator bearing.

NOTE: This spacer MUST be installed to prevent interference with the alternator case.

Loctite thread locker #262 must be used on the thread for the M14 nut.

The M14 nut must be tightened to 40 –45 ft-lbs using an impact gun, as it is difficult to prevent the shaft from rotating while tightening.

**For Technical Assistance, Call Moroso's Tech Line at
(203) 458-0542, 458-0546 8:30am – 5:00pm Eastern Time**

MOROSO PERFORMANCE PRODUCTS, INC
80 CARTER DR • GUILFORD, CT 06437
Phone: (203) 453-6571 • Fax: (203) 453-6906

Visit Us At www.moroso.com



PART 23556

Pulley comes with a .10 thick spacer to be installed between the pulley and the alternator bearing.

NOTE: This spacer MUST be installed to prevent interference with the alternator case.

Loctite thread locker #262 must be used on the thread for the M14 nut.

The M14 nut must be tightened to 40 –45 ft-lbs using an impact gun, as it is difficult to prevent the shaft from rotating while tightening.

**For Technical Assistance, Call Moroso's Tech Line at
(203) 458-0542, 458-0546 8:30am – 5:00pm Eastern Time**

MOROSO PERFORMANCE PRODUCTS, INC
80 CARTER DR • GUILFORD, CT 06437
Phone: (203) 453-6571 • Fax: (203) 453-6906

Visit Us At www.moroso.com



PART 23556

Pulley comes with a .10 thick spacer to be installed between the pulley and the alternator bearing.

NOTE: This spacer MUST be installed to prevent interference with the alternator case.

Loctite thread locker #262 must be used on the thread for the M14 nut.

The M14 nut must be tightened to 40 –45 ft-lbs using an impact gun, as it is difficult to prevent the shaft from rotating while tightening.

**For Technical Assistance, Call Moroso's Tech Line at
(203) 458-0542, 458-0546 8:30am – 5:00pm Eastern Time**

MOROSO PERFORMANCE PRODUCTS, INC
80 CARTER DR • GUILFORD, CT 06437
Phone: (203) 453-6571 • Fax: (203) 453-6906

Visit Us At www.moroso.com



PART 23556

Pulley comes with a .10 thick spacer to be installed between the pulley and the alternator bearing.

NOTE: This spacer MUST be installed to prevent interference with the alternator case.

Loctite thread locker #262 must be used on the thread for the M14 nut.

The M14 nut must be tightened to 40 –45 ft-lbs using an impact gun, as it is difficult to prevent the shaft from rotating while tightening.

**For Technical Assistance, Call Moroso's Tech Line at
(203) 458-0542, 458-0546 8:30am – 5:00pm Eastern Time**

MOROSO PERFORMANCE PRODUCTS, INC
80 CARTER DR • GUILFORD, CT 06437
Phone: (203) 453-6571 • Fax: (203) 453-6906

Visit Us At www.moroso.com



PART 23556

Pulley comes with a .10 thick spacer to be installed between the pulley and the alternator bearing.

NOTE: This spacer MUST be installed to prevent interference with the alternator case.

Loctite thread locker #262 must be used on the thread for the M14 nut.

The M14 nut must be tightened to 40 –45 ft-lbs using an impact gun, as it is difficult to prevent the shaft from rotating while tightening.

**For Technical Assistance, Call Moroso's Tech Line at
(203) 458-0542, 458-0546 8:30am – 5:00pm Eastern Time**

MOROSO PERFORMANCE PRODUCTS, INC
80 CARTER DR • GUILFORD, CT 06437
Phone: (203) 453-6571 • Fax: (203) 453-6906

Visit Us At www.moroso.com



PART 23556

Pulley comes with a .10 thick spacer to be installed between the pulley and the alternator bearing.

NOTE: This spacer MUST be installed to prevent interference with the alternator case.

Loctite thread locker #262 must be used on the thread for the M14 nut.

The M14 nut must be tightened to 40 –45 ft-lbs using an impact gun, as it is difficult to prevent the shaft from rotating while tightening.

**For Technical Assistance, Call Moroso's Tech Line at
(203) 458-0542, 458-0546 8:30am – 5:00pm Eastern Time**

MOROSO PERFORMANCE PRODUCTS, INC
80 CARTER DR • GUILFORD, CT 06437
Phone: (203) 453-6571 • Fax: (203) 453-6906

Visit Us At www.moroso.com