

MOROSO Digital Gauge Instructions

P/N 89574 0-15 psi

P/N 89575 0-60 psi

P/N 89576 0-100 psi

Normal Display Mode

0.0

Press and hold (Zero) key over 5 seconds

-- 1 -

Release

CONT

(Zero) Key
and wait 1 sec

Hold (Zero) Key

Hold

Release

-- 2 -

Aon

(Zero) Key and
wait 1 sec

Aoff

Hold (Zero) Key

0180

Release

-- 3 -

PSI

(Zero) Key and
wait 1 sec

Bar

Hold (Zero) Key

Kgf/cm2

KPa

Release

-- 4 -

0.5

(Zero) Key
and wait 1 sec

0.2

0.1

Hold (Zero) Key
Release

-- 5 -

5

(Zero) Key and
wait 1 sec

4

3

Hold (Zero) Key

- END -

- 0000 -

LCD displays "Cont"(continue reading) and "Hold" (peak and hold) alternately. Press (ZERO) key to select when the function you want shown on the LCD. It will go back to normal display mode when the setting is done.

In the normal display mode, there will be an icon "H" shown at the bottom of the LCD when the selection is "Peak & Hold". If there is no selection it will go back to normal display mode after functions display alternately 10 rounds.

LCD displays "Aon" (AlwaysOn) and "Aoff" (AutoOff) alternately. Press (ZERO) key to select when the function you want shown on the LCD. When the selection is "Aon", it will go back to the normal display mode; when the selection is "Aoff", it will go to the auto-off time setting mode.

If there is no other selection, it will go back to normal display mode after functions display alternately 10 rounds.

The auto-off time value (unit: second) is shown on the LCD. Press (ON) or (ZERO) key to change the value. Each press will plus or minus 5 seconds. It will go back to the normal display mode when there is no key pressed over 3 seconds.

In the unit selection mode, the units are shown at the bottom of the LCD in the circulative order of PSI -> Bar -> Kgf/cm2 -> KPa no unit PSI. Press (ZERO) key to select when the function you want is shown on the LCD. It will go back to the normal display mode when the setting is done.

Assuming display unit is PSI, select 0.5, then displays and talks in increments decimal of 0.5 PSI. Default is decimal display 0.1

Setting for the speed of response: There are 5 levels to choose. When the number is smaller, the speed will be faster.

**For Technical Assistance, call Moroso's Tech Line
(203)-458-0542, 8:30am-5:00pm Eastern Time
MOROSO PERFORMANCE PRODUCTS, INC.
80 CARTER DRIVE
GUILFORD, CT 06437
www.moroso.com**