One (1) Circuit Board (with Speedometer, Tachometer, Voltmeter, Water Temp., Fuel Level, Oil Pressure Gauge, and Clock One (1) Smoked Acrylic Lens & Overlay One (1) Temperature Sending Unit (S8013 OR S8023) - 1/8" NPT, 1/2" NPT Bushing One (1) Pressure Sending Unit (S8868) - 1/8" NPT, 0-100 PSI Oil Pressure One (1) Universal Speedometer Sensor (\$9013) - 7/8" NPT Industry Standard threads One (1) Mounting Kit

Two(2) - $10/32 \times 1$ " screws Eight (8) #8-32 x 3/8 in Pan Head Machine screws

Two(2) #10x3/8"-Nylon spacers Four (4) #8 x 1" Threaded Standoffs/separators

Two(2) #10- Nvlon washers Four (4) Attachment Brackets

Two(2) -10/32 Nylock nut