

Installation Instructions for 60350 & 60352 Transmission Cooler

Updated 09/09/10

1. Transmission cooler should be mounted to a secure protected location with adequate airflow.
2. The transmission cooler should be spliced "inline" with the return line to the transmission. Check with your transmission manufacturer or shop manual to determine which line is the return.
3. Use the four mounting holes in the transmission cooler brackets and suitable hardware to mount the unit. We recommend use of Vibration Isolator Kit 555-40686 or 555-40687 as space allows.
4. We recommend the use of a liquid Teflon sealant on fittings to reduce the risk of leaks.

To plumb with -AN lines see JEG'S catalog or visit us online!



1-800-345-4545 jeps.com