



JET POWERTECH PULLEYS

PART # 90140

1. Remove alternator belt.
2. Remove belt and harmonic balancer. **Note direction of cast arrow**
3. Remove alternator pulley and spacer.
4. Install underdrive balancer with mark in same location as cast arrow. Install alternator pulley.
5. Install Gates belt #K060615 **Note:** you may cross reference the Gates belt # to any other brand of belt.
6. *With the JET pulley kit installed, a reduction in charging at idle is normal. It is best to drive in a gear sufficient to maintain 1500 rpm or greater in order to maintain a good charge in the battery. Avoid prolonged idle especially in hot weather or with AC or headlights in use.*

JET Performance Products

17491 Apex Circle

Huntington Beach, CA 92647

714-848-5515 fax 714-847-6290 www.jetchip.com