



409S[®] Stainless Steel

Installation diagram for:
SYSTEM #81068
2 1/2" SB CHEVY MANIFOLD DOWNPIPES
1964-81 A-BODY & 1967-81 F-BODY
NOT FOR USE WITH HEAT RISER VALVE
NOT FOR 1962-67 NOVA

