

INSTALLATION INSTRUCTIONS

MSD Rotor for Honda/Acura Engines **PN 8090/PN 8092**

Parts Included:

- 1 - Rotor
- 1 - Screw and Lock Washer

The MSD Rotor will install to stock Honda/Acura distributors with a factory style cap or with MSD's line of Extreme Power Caps. Consult the chart below to confirm that you have the correct rotor for your application. It is recommended to install a new distributor cap with the rotor. MSD's caps are listed in the chart in Figure 1.

Year	Model	Engine	Notes	Rotor	DISTRIBUTOR CAPS			
ACURA					Black	Red	Extreme	OE Extreme
'97 (Only)	CL	2.2L	w/Hit. Dist.		PN 8291			
'98-'99	Acura CL	2.3L	w/Hit. Dist.		PN 8294			
'88-'91	Integra	1.6L/1.8L	w/Tec Dist.	PN 8090	PN 8290	PN 82901	PN 82902	PN 8295
'92-'93	Integra (All)	1.7L/1.8L	w/Tec Dist.		PN 8292	PN 82921	PN 82922	PN 8296
'94-'01	Integra GS, LS, RS	1.8L	w/Tec Dist.	PN 8092	PN 8292	PN 82921	PN 82922	PN 8296
'94-'01	Integra GS-R/Type-R	1.8L	w/Tec Dist.	PN 8092	PN 8293			
HONDA								
'90-'91	Accord	2.2L	w/Tec Dist.		PN 8292	PN 82921	PN 82922	PN 8296
'94-'97	Accord EX	2.2L	w/Hit. Dist.		PN 8291			
'98-'02	Accord DX (Only)	2.3L	w/Tec Dist.	PN 8092	PN 8292	PN 82921	PN 82922	PN 8296
'98-'02	Accord EX, LX, SE	2.3L	w/Hit. Dist.		PN 8294			
'88-'91	Civic, CRX	1.5L/1.6L	w/Tec Dist.	PN 8090	PN 8290	PN 82901	PN 82902	PN 8295
'93-'97	Civic Del Sol	1.5L/1.6L	w/Tec Dist.	PN 8092	PN 8292	PN 82921	PN 82922	PN 8296
'92-'00	Civic/Si (Exc. '96-'00 HX)	1.5L/1.6L	w/Tec Dist.	PN 8092	PN 8292	PN 82921	PN 82922	PN 8296
'96-'00	Civic HX (Only)	1.6L	w/Hit. Dist.		PN 8291			
'97-'01	CRV	2.0L	w/Tec Dist.	PN 8092	PN 8292	PN 82921	PN 82922	PN 8296
'95-'97	Odyssey	2.2L	w/Hit. Dist.		PN 8291			
'98 (Only)	Odyssey	2.3L	w/Hit. Dist.		PN 8294			

Figure 1 Rotor Application Chart.

1. Remove the distributor cap. If you choose to remove the spark plug wires, be sure to mark their location on the cap.
2. For the PN 8090 Rotor, you will need to remove the distributor's dust cover (Figure 2).
3. For the PN 8092 Rotor you may need to rotate the engine to access the rotor retaining screw. Once the screw is accessible, remove it and pull the rotor off (Figure 3).
4. Install the MSD Rotor and the retaining screw with washer. Install the distributor cap.

MSD **IGNITION** **INSTALLATION INSTRUCTIONS**

FOR PN 8090 ONLY




Figure 2 Removing Dust Cover

ROTOR RETAINING SCREW




Figure 3 Replacing the Rotor.

Service

In case of malfunction, this MSD component will be repaired free of charge according to the terms of the warranty. When returning MSD components for service, Proof of Purchase must be supplied for warranty verification. After the warranty period has expired, repair service is charged based on a minimum and maximum charge.

Send the unit prepaid with proof of purchase to the attention of: **Customer Service Department, MSD Ignition, 12120 Esther Lama, Suite 114, El Paso, Texas 79936.**

When returning the unit for repair, leave all wires at the length in which you have them installed. Be sure to include a detailed account of any problems experienced, and what components and accessories are installed on the vehicle.

The repaired unit will be returned as soon as possible after receipt, COD for any charges. (Ground shipping is covered by warranty). All units are returned regular UPS unless otherwise noted. For more information, call the MSD Customer Service Line (915) 855-7123. MSD technicians are available from 8:00 a.m. to 5:00 p.m. Monday - Friday (mountain time).

Limited Warranty

MSD IGNITION warrants MSD Ignition products to be free from defects in material and workmanship under normal use and if properly installed for a period of one year from date of purchase. If found to be defective as mentioned above, it will be replaced or repaired if returned prepaid along with proof of date of purchase. This shall constitute the sole remedy of the purchaser and the sole liability of MSD Ignition. To the extent permitted by law, the foregoing is exclusive and in lieu of all other warranties or representations whether expressed or implied, including any implied warranty of merchantability or fitness. In no event shall MSD Ignition be liable for special or consequential damages.