

Spohn Performance, Inc.

494 E Lincoln Ave Myerstown, PA 17067

1-888-365-6064 www.spohn.net

Part# SRK-F-8292 – Steering Linkage Rebuild Kit 1982-1992 GM F-Body

Kit Components

<u>Qty</u>	<u>Part #</u>	<u>Description</u>
1	K6249	Idler Arm
2	ES2226RL	Outer Tie Rod End
1	ES2227RL	Inner Tie Rod End
1	984	Tie Rod Adjusters
1	DS1049	Center Link

Notes:

- One end of the tie rod adjuster has hash marks. That end is LH threads and the other end is RH threads.
- Use anti-seize compound on all threads (very important, do not skip!).
- The tie rod ends should have a minimum of 7/8" of thread engagement inside of the tie rod adjusters for proper safe thread engagement.