

Sender ohm Range

PSI	ohms	tol
0-2	242	227-257
3-7	182	155-210
50	103	92-114
100	35	22-49