







2011 DURANGO

DOOR ENTRY SILL



1



2



97°F
35°C

52°F
15°C






FRONT




3 2X





4 2X

COMPLETELY REMOVE THE BACKING (LINER) OF THE TAPE.




5 2X




REAR

6 2X



7 2X COMPLETELY REMOVE THE BACKING (LINER) OF THE TAPE.



8 2X