

Part No.

22825-01

Chrysler 727,
518 (46RH/RE),
618 (47RH/RE)



INSTALLATION INSTRUCTIONS:

1. Remove the pan and valve body to expose the bottom of the transmission.
2. Remove the adjusting screw from the band.
3. Remove the original strut.
4. Insert the **22825-01** strut with the flat surface facing away from the band.
5. Replace the adjusting screw and set to manufacturer's standards.