



Part #64700/64701

The bolt pattern on this pulley has one offset bolt hole. Index the bolt pattern on this pulley with the bolt pattern on the dampener.

MOROSO PERFORMANCE PRODUCTS, INC
80 CARTER DR • GUILFORD, CT 06437
Phone: (203) 453-6571 • Fax: (203) 453-6906

Visit Us At www.moroso.com



Part #64700/64701

The bolt pattern on this pulley has one offset bolt hole. Index the bolt pattern on this pulley with the bolt pattern on the dampener.

MOROSO PERFORMANCE PRODUCTS, INC
80 CARTER DR • GUILFORD, CT 06437
Phone: (203) 453-6571 • Fax: (203) 453-6906

Visit Us At www.moroso.com



Part #64700/64701

The bolt pattern on this pulley has one offset bolt hole. Index the bolt pattern on this pulley with the bolt pattern on the dampener.

MOROSO PERFORMANCE PRODUCTS, INC
80 CARTER DR • GUILFORD, CT 06437
Phone: (203) 453-6571 • Fax: (203) 453-6906

Visit Us At www.moroso.com



Part #64700/64701

The bolt pattern on this pulley has one offset bolt hole. Index the bolt pattern on this pulley with the bolt pattern on the dampener.

MOROSO PERFORMANCE PRODUCTS, INC
80 CARTER DR • GUILFORD, CT 06437
Phone: (203) 453-6571 • Fax: (203) 453-6906

Visit Us At www.moroso.com



Part #64700/64701

The bolt pattern on this pulley has one offset bolt hole. Index the bolt pattern on this pulley with the bolt pattern on the dampener.

MOROSO PERFORMANCE PRODUCTS, INC
80 CARTER DR • GUILFORD, CT 06437
Phone: (203) 453-6571 • Fax: (203) 453-6906

Visit Us At www.moroso.com



Part #64700/64701

The bolt pattern on this pulley has one offset bolt hole. Index the bolt pattern on this pulley with the bolt pattern on the dampener.

MOROSO PERFORMANCE PRODUCTS, INC
80 CARTER DR • GUILFORD, CT 06437
Phone: (203) 453-6571 • Fax: (203) 453-6906

Visit Us At www.moroso.com



Part #64700/64701

The bolt pattern on this pulley has one offset bolt hole. Index the bolt pattern on this pulley with the bolt pattern on the dampener.

MOROSO PERFORMANCE PRODUCTS, INC
80 CARTER DR • GUILFORD, CT 06437
Phone: (203) 453-6571 • Fax: (203) 453-6906

Visit Us At www.moroso.com



Part #64700/64701

The bolt pattern on this pulley has one offset bolt hole. Index the bolt pattern on this pulley with the bolt pattern on the dampener.

MOROSO PERFORMANCE PRODUCTS, INC
80 CARTER DR • GUILFORD, CT 06437
Phone: (203) 453-6571 • Fax: (203) 453-6906

Visit Us At www.moroso.com